

USS Greenville Engineering logs:

9 February, 2001

Time	Remarks
0001 – 0756	Normal plant startup and underway preparations, (no deficiencies).
0757	Underway
0850	Secured Maneuvering watch
0903	Electric Plant Normal Full Power Lineup
1100	[REDACTED]
1152	LTJGL assumed watch as EOOW
1320	[REDACTED]
1350	Surfaced the ship, COLLISION DURING EMBT BLOW, forward shaft seals failed, indication of shaft wobble
1819	LTJGL assumed watch as EOOW
1830	[REDACTED]

(b)(1)

(b)(3)/(b)(6)

(b)(3)/(b)(6)

10 February, 2001

Time	Remarks
0140	LTJGL assumed watch as EOOW
0504	[REDACTED]
0516	[REDACTED]
0541	[REDACTED]
0622	LTJGL assumed watch as EOOW

(b)(1)

(b)(3)/(b)(6)

(b)(3)/(b)(6)

(NOTE: Unclassified version of Engineering Logs)